



AVR128DB28/32/48/64

AVR128DB28/32/48/64 Silicon Errata and Data Sheet Clarifications

The AVR128DB28/32/48/64 devices you have received conform functionally to the current device data sheet (www.microchip.com/DS40002247), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the AVR128DB28/32/48/64 devices.

Notes:

- This document summarizes all the silicon errata issues from all revisions of silicon, previous as well as current
- Refer to the Device/Revision ID section in the current device data sheet (www.microchip.com/DS40002247) for more detailed information on Device Identification and Revision IDs for your specific device, or contact your local Microchip sales office for assistance

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- X Erratum is applicable.

Peripheral	Short Description	Valid for Silicon Revision	
		Rev. A4 ⁽¹⁾	Rev. A5
Device	2.2.1 Some Reserved Fuse Bits are '1'	X	-
ADC	2.3.1 Increased Offset in Single-Ended Mode	X	-
CCL	2.4.1 The Entire CCL Module Needs to be Disabled to Change the Configuration of a Single LUT	X	X
	2.4.2 The LINK Input Source Selection for LUT3 is Not Functional on 28- and 32-pin Devices	X	-
CLKCTRL	2.5.1 External Clock/Crystal Status Bit is Not Set When the External Clock Source is Ready	X	-
	2.5.2 RUNSTDBY is Not Functional When Using External Clock Sources	X	-
PORT	2.6.1 PD0 Input Buffer is Floating	X	X
OPAMP	2.7.1 OPAMP Consume More Power Than Expected	X	-
	2.7.2 The Input Range Select is Read-Only	X	-
RSTCTRL	2.8.1 BOD Registers Not Reset When UPDI is Enabled	X	-
TWI	2.9.1 The Output Pin Override Does Not Function as Expected	X	X
USART	2.10.1 Open-Drain Mode Does Not Work When TXD is Configured as Output	X	X
	2.10.2 Start-of-Frame Detection Can Unintentionally Be Enabled in Active Mode when RXCIF is '0'	X	X
ZCD	2.11.1 All ZCD Output Selection Bits are Tied to the ZCD0 Bit	X	-

Note:

1. This revision is the initial release of the silicon.

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X Erratum is applicable.

2.2 Device

2.2.1 Some Reserved Fuse Bits are '1'

For material with date code 2021 (year 2020, week 21) or older, the default fuse values are not compliant with the data sheet.

The fuse values will read out as listed below:

- BODCFG = 0x10
- OSCCFG = 0x78 (Device will use the OSCHF clock source)
- SYSCFG0 = 0xF6
- SYSCFG1 = 0xE8

Work Around

None.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

2.3 ADC - Analog to Digital Converter

2.3.1 Increased Offset in Single-Ended Mode

The ADC result has a typical offset of -3 mV ($V_{DD} = 3.0V$, Temp = 25°C) when the ADC is operating in single-ended mode.

The typical offset drift vs. V_{DD} is -0.3 mV/V, and the typical offset drift vs. temperature is -0.02 mV/°C.

Work Around

To reduce the offset, use the ADC in differential mode and connect the negative ADC input pin externally to GND.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

2.4 CCL - Configurable Custom Logic

2.4.1 The Entire CCL Module Needs to be Disabled to Change the Configuration of a Single LUT

To reconfigure a LUT, the CCL module will first need to be disabled. Since the enable control bit will disable all the LUTs, this might cause issues if different LUTs are used for independent tasks.

Work Around

None

Affected Silicon Revisions

Rev. A4	Rev. A5
X	X

2.4.2 The LINK Input Source Selection for LUT3 is Not Functional on 28- and 32-pin Devices

When using INSELn to select the LINK input option for LUT3, the actual output connection from LUT0 does not get connected as an input to LUT3. This occurs only on the 28-pin and 32-pin devices.

Work Around

Do not select LINK mode for LUT3 with INSELn.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

2.5 CLKCTRL - Clock System

2.5.1 External Clock/Crystal Status Bit is Not Set When the External Clock Source is Ready

If an external clock source is selected (SELHF in XOSCHFCTRLA is '1') and the Run Standby (RUNSTDBY) bit in XOSCHFCTRLA is '1' without the clock source being requested, the External Clock/Crystal Status (EXTS) bit will not be set to '1' when the external clock source is ready.

Work Around

Request the clock from RTC or TCD before checking the EXTS bit.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

2.5.2 RUNSTDBY is Not Functional When Using External Clock Sources

When using any of the External Clock Sources, the related Run Standby bit (RUNSTDBY), found in the XOSC32KCTRLA register, will not force the oscillator source to stay on during sleep modes.

Work Around

Enable a peripheral, with the external oscillator as the clock source, to keep the clock source active during sleep modes.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

2.6 PORT - I/O Pin Configuration**2.6.1 PD0 Input Buffer is Floating**

On 28-pin and 32-pin package parts, the PD0 input buffer is floating. Because the default direction setting for PD0 is as an input pin, this may cause unexpected current consumption.

Work Around

Disable the PD0 input (ISC in PORTD.PIN0CTRL) or configure the pin as an output (bit 0 in PORTD.DIR).

Affected Silicon Revisions

Rev. A4	Rev. A5
X	X

2.7 OPAMP - Analog Signal Conditioning**2.7.1 OPAMP Consume More Power Than Expected**

The OPAMP module consumes up to three times more current than specified when the output is driven closer to either the upper or lower rails.

Work Around

None.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

2.7.2 The Input Range Select is Read-Only

The Input Range Select (IRSEL) bit is read-only. When the Analog Signal Conditioning (OPAMP) peripheral is active, the input voltage range will be rail-to-rail.

Work Around

None.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

2.8 RSTCTRL - Reset Controller

2.8.1 BOD Registers Not Reset When UPDI is Enabled

The registers VLMCTRL, INTCTRL and INTFLAGS in BOD will not be reset by other reset sources than POR if the UPDI is enabled.

Work Around

None

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

2.9 TWI - Two-Wire Interface

2.9.1 The Output Pin Override Does Not Function as Expected

When TWI is enabled, it overrides the output pin driver, but not the output value. So when the value in the PORTx.OUT register is '1', for the pins corresponding to the SDA or SCL, the output on the line will always be high.

Work Around

Ensure that the value in the PORTx.OUT register corresponding to the SCL and SDA pins are '0' before enabling the TWI.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	X

2.10 USART - Universal Synchronous and Asynchronous Receiver and Transmitter

2.10.1 Open-Drain Mode Does Not Work When TXD is Configured as Output

When the USART TXD pin is configured as an output, it can drive the pin high regardless of Open-Drain mode being enabled or not.

Work Around

Configure the TXD pin as an input by writing the corresponding bit in PORTx.DIR to '0' when using Open-Drain mode.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	X

2.10.2 Start-of-Frame Detection Can Unintentionally Be Enabled in Active Mode when RXCIF is '0'

The Start-of-Frame Detector can unintentionally be enabled when the device is in Active mode and when the Receive Complete Interrupt Flag (RXCIF) in the USARTn.STATUS register is '0'. If the Receive Data (RXDATA) registers are read while receiving new data, RXCIF is cleared, and the Start-of-Frame Detector will be enabled and falsely detects

the following falling edge as a start bit. When the Start-of-Frame Detector detects a start condition, the frame reception is restarted, resulting in corrupt received data.

Note that the USART Receive Start Interrupt Flag (RXSIF) always is '0' when in Active mode, so no interrupt will be triggered.

Work Around

Disable Start-of-Frame Detection by writing '0' to the Start-of-Frame Detection Enable (SFDEN) bit in the USART Control B (USARTn.CTRLB) register, when the device is in Active mode. Enable it again by writing the bit to '1' before transitioning to Standby sleep mode. This work around depends on a protocol preventing a new incoming frame when re-enabling Start-of-Frame Detection. Re-enabling Start-of-Frame Detection, while a new frame is already incoming, will result in corrupted received data.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	X

2.11 ZCD - Zero-Cross Detector

2.11.1 All ZCD Output Selection Bits are Tied to the ZCD0 Bit

The output selection bits, ZCD1 and ZCD2, are tied to bit ZCD0. When writing a value to ZCD0, all three ZCD outputs are switched from the default pin setting to the alternative pin setting. When writing to either ZCD1 or ZCD2, nothing happens.

Work Around

None.

Affected Silicon Revisions

Rev. A4	Rev. A5
X	-

3. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (www.microchip.com/DS40002247).

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1 None

There are no known data sheet clarifications as of this publication date.

4. Document Revision History

Note: The data sheet clarification document revision is independent of the die revision and the device variant (last letter of the ordering number).

4.1 Revision History

Doc. Rev.	Date	Comments
A	08/2020	Initial document release

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features of the Microchip devices. We believe that these methods require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-6626-0

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p>Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Tel: 480-792-7277 Technical Support: www.microchip.com/support Web Address: www.microchip.com</p> <p>Atlanta Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p>Austin, TX Tel: 512-257-3370</p> <p>Boston Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p>Chicago Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p>Dallas Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p>Detroit Novi, MI Tel: 248-848-4000</p> <p>Houston, TX Tel: 281-894-5983</p> <p>Indianapolis Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p>Los Angeles Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p>Raleigh, NC Tel: 919-844-7510</p> <p>New York, NY Tel: 631-435-6000</p> <p>San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270</p> <p>Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078</p>	<p>Australia - Sydney Tel: 61-2-9868-6733</p> <p>China - Beijing Tel: 86-10-8569-7000</p> <p>China - Chengdu Tel: 86-28-8665-5511</p> <p>China - Chongqing Tel: 86-23-8980-9588</p> <p>China - Dongguan Tel: 86-769-8702-9880</p> <p>China - Guangzhou Tel: 86-20-8755-8029</p> <p>China - Hangzhou Tel: 86-571-8792-8115</p> <p>China - Hong Kong SAR Tel: 852-2943-5100</p> <p>China - Nanjing Tel: 86-25-8473-2460</p> <p>China - Qingdao Tel: 86-532-8502-7355</p> <p>China - Shanghai Tel: 86-21-3326-8000</p> <p>China - Shenyang Tel: 86-24-2334-2829</p> <p>China - Shenzhen Tel: 86-755-8864-2200</p> <p>China - Suzhou Tel: 86-186-6233-1526</p> <p>China - Wuhan Tel: 86-27-5980-5300</p> <p>China - Xian Tel: 86-29-8833-7252</p> <p>China - Xiamen Tel: 86-592-2388138</p> <p>China - Zhuhai Tel: 86-756-3210040</p>	<p>India - Bangalore Tel: 91-80-3090-4444</p> <p>India - New Delhi Tel: 91-11-4160-8631</p> <p>India - Pune Tel: 91-20-4121-0141</p> <p>Japan - Osaka Tel: 81-6-6152-7160</p> <p>Japan - Tokyo Tel: 81-3-6880-3770</p> <p>Korea - Daegu Tel: 82-53-744-4301</p> <p>Korea - Seoul Tel: 82-2-554-7200</p> <p>Malaysia - Kuala Lumpur Tel: 60-3-7651-7906</p> <p>Malaysia - Penang Tel: 60-4-227-8870</p> <p>Philippines - Manila Tel: 63-2-634-9065</p> <p>Singapore Tel: 65-6334-8870</p> <p>Taiwan - Hsin Chu Tel: 886-3-577-8366</p> <p>Taiwan - Kaohsiung Tel: 886-7-213-7830</p> <p>Taiwan - Taipei Tel: 886-2-2508-8600</p> <p>Thailand - Bangkok Tel: 66-2-694-1351</p> <p>Vietnam - Ho Chi Minh Tel: 84-28-5448-2100</p>	<p>Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p>Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829</p> <p>Finland - Espoo Tel: 358-9-4520-820</p> <p>France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p>Germany - Garching Tel: 49-8931-9700</p> <p>Germany - Haan Tel: 49-2129-3766400</p> <p>Germany - Heilbronn Tel: 49-7131-72400</p> <p>Germany - Karlsruhe Tel: 49-721-625370</p> <p>Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p>Germany - Rosenheim Tel: 49-8031-354-560</p> <p>Israel - Ra'anana Tel: 972-9-744-7705</p> <p>Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p>Italy - Padova Tel: 39-049-7625286</p> <p>Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340</p> <p>Norway - Trondheim Tel: 47-72884388</p> <p>Poland - Warsaw Tel: 48-22-3325737</p> <p>Romania - Bucharest Tel: 40-21-407-87-50</p> <p>Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p>Sweden - Gothenberg Tel: 46-31-704-60-40</p> <p>Sweden - Stockholm Tel: 46-8-5090-4654</p> <p>UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>