

PIC16(L)F18426/46

PIC16(L)F18426/46 Family Silicon Errata and Data Sheet Clarification

Preface

The PIC16(L)F18426/46 devices that you have received conform functionally to the current device data sheet (www.microchip.com/DS40001985), except for the anomalies described in this document. The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the table below. The errata described in this document will be addressed in future revisions of the PIC16(L)F18426/46 silicon.




Notice: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of the 'Silicon Issue Summary' table apply to the current silicon revision (A1).

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate website (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

- Using the appropriate interface, connect the device to the hardware debugger.
- 2. Open an MPLAB IDE project.
- Configure the MPLAB IDE project for the appropriate device and hardware debugger.
- Based on the version of MPLAB IDE you are using, do one of the following:
 - For MPLAB IDE 8, select Programmer > Reconnect.
 - For MPLAB X IDE, select Window > Dashboard and click the Refresh Debug Tool Status icon (). 4.2.



Depending on the development tool used, the part number and Device Revision ID value appear in the Output

Table 1. Silicon Device Identification

Device ID	Revision ID	
Device in	A1	
0x30D2	0x8005	
0x30D3	0x8005	
0x30D4	0x8005	
0x30D5	0x8005	
	0x30D3 0x30D4	

Note: Refer to the Device/Revision ID section in the current "PIC16(L)F184XX Memory Programming Specification" (DS40001970) for a detailed information on Device Identification and Revision IDs for your specific device.

Errata DS80000799C-page 1 © 2020 Microchip Technology Inc.

Silicon Issue Summary

Module	Feature	Item No.	Issue Summary	Affected Revisions
				A1
NVM	WRERR bit Operation	1.1.1	NVMERR bit is set by device Reset after being cleared by software.	Х
MSSP	SPI	1.2.1	SSPBUF may be corrupted by writes to other GPR/SFRs.	Х
Electrical	Minimum V _{DD} Specification	1.3.1	V _{DD} Min. specifications are changed for LF devices only.	Х
Specifications	PFM Endurance	1.3.2	The PFM endurance is lower than specified.	Х
Analog-to-Digital Converter With Computation (ADC ²)	ADC ² Burst Average mode	1.4.1	ADC ² Burst Average mode while in "Non-Continuous Double Sample" mode is buggy.	Х
Windowed Watchdog Timer	Window Operation	1.5.1	Window feature of the WWDT does not operate correctly in DOZE mode.	Х
Device Configuration	CONFIG2	1.6.1	Bit 2 of PWRTS<1:0> in the CONFIG2 register is not functional.	Х
Note: Only those issue	es indicated in the last co	olumn appl	y to the current silicon revision.	

Silicon Errata Issues

1. Silicon Errata Issues



Notice: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the bold font in the following tables apply to the current silicon revision.

1.1 Module: Nonvolatile Memory (NVM)

1.1.1 WRERR Bit Operation

When a Reset is issued while an NVM high voltage operation is in progress, the WRERR bit in the NVMCON1 register is set as expected. After clearing the WRERR bit, if a Reset reoccurs, the WRERR bit is set again regardless of whether an NVM operation is in progress or not. A successful write operation will clear the WRERR condition.

Work around

None.

Affected Silicon Revisions

A 1				
X				

1.2 Module: Master Synchronous Serial Port (MSSP)

1.2.1 MSSP SPI Slave Mode

When operating in SPI Slave mode, if the incoming SCK clock signal arrives during any of the conditions below, the SSPBUF Transmit Shift Register (TSR) may become corrupted. The transmitted slave byte cannot be ensured to be correct, and the state of the WCOL bit may or may not indicate a write collision.

These conditions include:

- · A write to an SFR
- · A write to RAM following an SFR read
- · A write to RAM prior to an SFR read

Work around

Method 1 (Interrupt based using SS):

- Connect the SS line to both the SS input and either an INT or IOC input pin.
- 2. Enable INT or IOC interrupts (interrupt on falling edge if available, otherwise check that $\overline{SS} == 0$ when the interrupt occurs).
- 3. Load SSPBUF with the data to be transmitted.
- 4. Continue program execution.
- 5. When the Interrupt Service Routine (ISR) is invoked, do either of the following:
 - 5.1. Add a delay that ensures the first SCK clock will be complete, or
 - 5.2. Poll SSPSTAT.BF (while(BF == 0)) and wait for the transmission/reception to complete.

Method 2 (Bit polling based using \overline{SS}):

- Load SSPBUF with the data to be transmitted.
- 2. Poll the \overline{SS} line and wait for the \overline{SS} to go active (while(!PORTx. \overline{SS} == 0)).

- 3. When \overline{SS} is active ($\overline{SS} == 0$), do either of the following:
 - 3.1. Add a delay that ensures the first SCK clock will be complete, or
 - 3.2. Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

Once one of these two methods are complete, it is safe to return to program execution.

Method 3 (SS not available):

- Load SSPBUF with the data to be transmitted.
- Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

Affected Silicon Revisions

A 1				
X				

1.3 Module: Electrical Specifications

1.3.1 Minimum V_{DD} Specification for LF Devices

 $V_{DD\ MIN}$ parameter (D002) at -40°C to 25°C = 2.3V.

Table 1-1. Supply Voltage

PIC16(L)	F18426/46	6	Standa	Standard Operating Conditions (Unless Otherwise Stated)					
Param. No.	Sym.	Characteristic	Min.	Тур.	Max.	Units	Conditions		
D002	VDD		1.8	-	3.6	V	FOSC < 16 MHz, TA > 25°C		
			2.3	-	- 3.6 V FOSC < 16 MHz, -40°C < = TA < =		FOSC <u><</u> 16 MHz, -40°C < = TA < = 25°C		
			2.5		3.6		FOSC > 16 MHz		

Work around

None.

Affected Silicon Revisions

A 1				
Х				

1.3.2 Endurance of PFM is Lower than Specified

The minimum value for the Program Flash Memory (PFM) endurance specification called out as parameter number MEM30 is 1K cycles.

Work around

None.

Affected Silicon Revisions

A 1				
X				

1.4 Module: Analog-to-Digital Converter with Computation (ADCC)

1.4.1 ADCC Burst Average Mode

When the ADCC is operated in Burst Average mode (ADMD = 0b011 in the ADCON2 register) while enabling non-continuous operation and double-sampling (ADCONT = 0 in the ADCON0 register and ADDSEN = 1 in the ADCON1 register), the value in the ADCNT register does not increment beyond '0b1' toward the value in the ADRPT register.

Work around

When operating the ADCC in Burst Average mode with double-sampling, enable continuous operation of the module (ADCONT = 1 in the ADCON0 register) and set the Stop-on-Interrupt bit (the ADSOI bit in the ADCON3 register). After the interrupt occurs, perform appropriate threshold calculations in the software and retrigger ADCC as necessary.

Alternatively, if the CPU is in Low-Power Sleep mode, the ADCC in non-continuous Burst-Average mode can be operated with a single ADC conversion (ADDSEN = 0 in the ADCON1 register). Doing so compromises noise immunity for lower power consumption by preventing the device from waking up to perform threshold calculations in the software.

Affected Silicon Revisions

A1				
X				

1.5 Module: Windowed Watchdog Timer (WWDT)

1.5.1 Window Operation in Doze Mode

When the windowed mode of operation is enabled in Doze mode, a window violation error is issued even though the window is open and has been armed. This condition occurs only when the window size is set to a value other than 100% open.

Work around

Method 1:

Use the windowed mode of operation in any other than Doze mode. If disabling the Doze mode is not an option, use the WWDT module without the window being enabled.

Method 2:

If the device is in Doze mode, perform the arming process for the window in Normal mode and return to the Doze mode.

Method 3:

If there is an Interrupt Service Routine (ISR) in the application code, the arming within the window can be done inside the ISR with the ROI bit of the CPUDOZE register being set.

Affected Silicon Revisions

A 1				
X				

1.6 Module: Device Configuration

1.6.1 PWRTS<1> Power-up Timer Selection Not Implemented

Bit 2 of PWRTS<1:0> in the CONFIG2 register is not functional. This bit is the upper bit of the Power-Up Timer Selection bits, PWRTS <1:0>. This means that the functions selected by PWRTS = 11 and PWRTS = 10 are not available.

Work around

The other functions selected by PWRTS = 01 and PWRTS = 00 are available.

Affected Silicon Revisions

A 1				
X				

Appendix A: Revision History

2. Appendix A: Revision History

Doc Rev.	Date	Comments
С		Updating Electrical Spec. 1.3.1 description and added 1.3.2 Electrical Spec. silicon issue; Other minor corrections.
В	07/2018	Fixed typo in Table 1.
Α	07/2018	Initial document release.

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- Business of Microchip Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- · Distributor or Representative
- · Local Sales Office
- · Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- · Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features
 of the Microchip devices. We believe that these methods require using the Microchip products in a manner
 outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code
 protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code
 protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly
 evolving. We at Microchip are committed to continuously improving the code protection features of our products.
 Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act.
 If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue
 for relief under that Act.

Legal Notice

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, Anyln, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-7115-8

AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro, µVision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere.

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

Australia				
2355 West Chandler Blvd. Tel: 61-2-9686-0733 Tel: 91-90-3090-44444 India - New Delhi Fax: 480-792-7277 China - Chengdu Tel: 91-11-4160-8631 Denmark - Copenhagen Tel: 480-792-7277 China - Chengdu India - Pume Tel: 48-4485-8910 Tel: 480-792-7277 China - Chengdu India - Pume Tel: 48-4485-8910 Tel: 480-792-7277 China - Chengdu India - Pume Tel: 48-4485-8910 Tel: 480-792-7277 China - Chengdu India - Pume Tel: 48-4485-8910 Tel: 480-792-7277 Tel: 68-2-86865-5511 Tel: 91-91-91-910 Tel: 48-8485-8910 Tel: 480-7868-8700 Tel: 591-591-590 Tel: 591	AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Chandler, AZ 88224-6199	Corporate Office	Australia - Sydney	India - Bangalore	Austria - Wels
Tel: 486-792-7200	2355 West Chandler Blvd.	Tel: 61-2-9868-6733	Tel: 91-80-3090-4444	Tel: 43-7242-2244-39
Fax: 480-782-7277	Chandler, AZ 85224-6199	China - Beijing	India - New Delhi	Fax: 43-7242-2244-393
Technical Support	Tel: 480-792-7200	Tel: 86-10-8569-7000	Tel: 91-11-4160-8631	Denmark - Copenhagen
Web Address	Fax: 480-792-7277	China - Chengdu	India - Pune	Tel: 45-4485-5910
Web Address: Tel: 86-28-8980-9588	Technical Support:	Tel: 86-28-8665-5511	Tel: 91-20-4121-0141	Fax: 45-4485-2829
Web Address:	www.microchip.com/support	China - Chongqing	Japan - Osaka	Finland - Espoo
Atlanta		Tel: 86-23-8980-9588	Tel: 81-6-6152-7160	Tel: 358-9-4520-820
Duluth, GA	www.microchip.com	China - Dongguan	Japan - Tokyo	France - Paris
Tel: 678-957-9614	Atlanta	Tel: 86-769-8702-9880	Tel: 81-3-6880- 3770	Tel: 33-1-69-53-63-20
Fax: 678-957-1455	Duluth, GA	China - Guangzhou	Korea - Daegu	Fax: 33-1-69-30-90-79
Austin_TX	Tel: 678-957-9614	Tel: 86-20-8755-8029	Tel: 82-53-744-4301	Germany - Garching
Tel: 512-257-3370	Fax: 678-957-1455	China - Hangzhou	Korea - Seoul	Tel: 49-8931-9700
Boston	Austin, TX	Tel: 86-571-8792-8115	Tel: 82-2-554-7200	Germany - Haan
Mestborough, MA	Tel: 512-257-3370	China - Hong Kong SAR	Malaysia - Kuala Lumpur	Tel: 49-2129-3766400
Tel: 774-760-0087 Fax: 774-760-0088 China - Qinjadao Philippines - Manila Tel: 49-721-625370 Tel: 86-532-8502-7355 Tel: 63-634-9065 Germany - Karlsruhe Tel: 49-721-625370 Tel: 49-721-6	Boston	Tel: 852-2943-5100	Tel: 60-3-7651-7906	Germany - Heilbronn
Fax: 774-760-0088	Westborough, MA	China - Nanjing	Malaysia - Penang	Tel: 49-7131-72400
Tel: 86-532-8502-7355 Tel: 63-2-634-9065 Germany - Munich	Tel: 774-760-0087	Tel: 86-25-8473-2460	Tel: 60-4-227-8870	Germany - Karlsruhe
Itasca, IL	Fax: 774-760-0088	China - Qingdao	Philippines - Manila	Tel: 49-721-625370
Tel: 630-285-0071 Fax: 630-285-0075 China - Shenyang Tel: 86-24-234-2829 Tel: 86-24-234-2829 Tel: 86-35-77-8366 Tel: 49-8031-354-560 Addison, TX China - Shenzhen Tel: 86-35-77-8366 Tel: 49-8031-354-560 Tel: 49-8031-354-560 Tel: 86-755-8864-2200 Tel: 866-72-13-7830 Tel: 972-918-744-7705 Tel: 86-755-8864-2200 Tel: 866-72-13-7830 Tel: 972-9-744-7705 Tel: 86-82-2508-8600 Tel: 866-72-13-7830 Tel: 972-9-744-7705 Tel: 86-82-2508-8600 Tel: 866-72-2508-8600 Tel: 866-72-2508-8600 Tel: 39-0331-742611 Novi, MI China - Suzhou Tel: 86-22-2508-8600 Tel: 86-22-2508-8600 Tel: 38-24-75980-5300 Tel: 66-2-694-1351 Tel: 86-28-848-4000 Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Tel: 86-28-883-7252 Tel: 86-89-883-7252 Tel: 86-89-89-893 Tel: 86-7-213-783-1 Tel: 86-7-213-783-0 Tel: 8	Chicago	Tel: 86-532-8502-7355	Tel: 63-2-634-9065	Germany - Munich
Fax: 630-285-0075	Itasca, IL	China - Shanghai	Singapore	Tel: 49-89-627-144-0
Dallas	Tel: 630-285-0071	Tel: 86-21-3326-8000	Tel: 65-6334-8870	Fax: 49-89-627-144-44
Addison, TX	Fax: 630-285-0075	China - Shenyang	Taiwan - Hsin Chu	Germany - Rosenheim
Tel: 972-818-7423	Dallas	Tel: 86-24-2334-2829	Tel: 886-3-577-8366	Tel: 49-8031-354-560
Fax: 972-818-2924	Addison, TX	China - Shenzhen	Taiwan - Kaohsiung	Israel - Ra'anana
Tel: 86-186-6233-1526	Tel: 972-818-7423	Tel: 86-755-8864-2200	Tel: 886-7-213-7830	Tel: 972-9-744-7705
Novi, MI	Fax: 972-818-2924	China - Suzhou	Taiwan - Taipei	Italy - Milan
Tel: 248-848-4000 Houston, TX China - Xian Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Vietnam - Ho Chi Minh Tel: 39-049-7625286 Tel: 39-049-7625286 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 31-416-690399 Noblesville, IN Tel: 86-592-2388138 Tel: 317-773-8323 China - Zhuhai Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 317-536-2380 Los Angeles Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9523 Fax: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 40-8-5090-4654 UK - Wokingham	Detroit	Tel: 86-186-6233-1526	Tel: 886-2-2508-8600	Tel: 39-0331-742611
Houston, TX	Novi, MI	China - Wuhan	Thailand - Bangkok	Fax: 39-0331-466781
Tel: 291-894-5983 Tel: 86-29-8833-7252 Indianapolis China - Xiamen Tel: 86-592-2388138 Tel: 317-773-8323 China - Zhuhai Tel: 86-592-2388138 Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 317-536-2380 Los Angeles Los Angeles Tel: 949-462-9523 Fax: 949-462-9608 Tel: 949-462-9608 Tel: 919-844-7510 Rew York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 86-29-8833-7252 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 81-28-5448-2100 Netherlands - Drunen Tel: 31-416-690349 Fax: 31-416-690340 Norway - Trondheim Tel: 47-7284388 Poland - Warsaw Tel: 47-7284388 Poland - Warsaw Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham	Tel: 248-848-4000	Tel: 86-27-5980-5300	Tel: 66-2-694-1351	Italy - Padova
Indianapolis China - Xiamen Tel: 31-416-690399 Noblesville, IN Tel: 86-592-2388138 Fax: 31-416-690340 Tel: 317-773-8323 China - Zhuhai Norway - Trondheim Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Tel: 317-536-2380 Poland - Warsaw Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham	Houston, TX	China - Xian	Vietnam - Ho Chi Minh	Tel: 39-049-7625286
Tel: 86-592-2388138 Fax: 31-416-690340 Tel: 317-773-8323 China - Zhuhai Tel: 47-72884388 Tel: 317-536-2380 Foland - Warsaw Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 34-91-708-08-90 Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg Tel: 40-31-704-60-40 Sweden - Stockholm Tel: 40-8-5090-4654 UK - Wokingham	Tel: 281-894-5983	Tel: 86-29-8833-7252	Tel: 84-28-5448-2100	Netherlands - Drunen
Tel: 317-773-8323 China - Zhuhai Norway - Trondheim Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 408-735-9110	Indianapolis	China - Xiamen		Tel: 31-416-690399
Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Tel: 317-536-2380 Poland - Warsaw Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm Tel: 408-735-9110 UK - Wokingham	Noblesville, IN	Tel: 86-592-2388138		Fax: 31-416-690340
Tel: 317-536-2380	Tel: 317-773-8323	China - Zhuhai		Norway - Trondheim
Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 34-91-708-08-90 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 408-735-9110	Fax: 317-773-5453	Tel: 86-756-3210040		Tel: 47-72884388
Mission Viejo, CA Tel: 949-462-9523 Tel: 949-462-9608 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Tel: 34-91-708-08-91 Tel: 46-31-708-08-91 Tel: 46-31-704-60-40 Tel: 46-31-704-60-40 Tel: 46-8-5090-4654 UK - Wokingham	Tel: 317-536-2380			Poland - Warsaw
Tel: 949-462-9523 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 40-21-407-87-50 Spain - Madrid Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Tel: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham	Los Angeles			Tel: 48-22-3325737
Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham	Mission Viejo, CA			Romania - Bucharest
Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-735-9110 Tel: 34-91-708-08-90 Fax: 34-91-708-08-90 Fax: 34-91-708-08-90 Fax: 34-91-708-08-90 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham	Tel: 949-462-9523			Tel: 40-21-407-87-50
Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham	Fax: 949-462-9608			Spain - Madrid
Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham	Tel: 951-273-7800			Tel: 34-91-708-08-90
New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham	Raleigh, NC			Fax: 34-91-708-08-91
Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham	Tel: 919-844-7510			Sweden - Gothenberg
San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham	New York, NY			Tel: 46-31-704-60-40
Tel: 408-735-9110 UK - Wokingham	Tel: 631-435-6000			Sweden - Stockholm
	San Jose, CA			Tel: 46-8-5090-4654
Tol. 400 426 4270	Tel: 408-735-9110			UK - Wokingham
1e1: 440-430-4270	Tel: 408-436-4270			Tel: 44-118-921-5800
Canada - Toronto Fax: 44-118-921-5820	Canada - Toronto			Fax: 44-118-921-5820
Tel: 905-695-1980	Tel: 905-695-1980			
Fax: 905-695-2078	Fax: 905-695-2078			