
P1 PCI edge connector should have v-cut to make insertion in PCI connector easier.
P1 PCI_CON
JP2 pin 20 should not have pin. This pin should be missing to ensure that connector fits with all ATA cables.
IC1 SN74LVC8T245
IC2 SN74LVC8T245
IC3 SN74LVC8T245
IC4 SN74LVC8T245
IC5 SN74LVC8T245
JP2 HEADER 20X2
JP3 HEADER 3
JP1 HEADER 3
U1 NC7S04M5X_NL
Select one
ATMEL Norway AS
Vestre Rosten 79
N-7075 Tiller
Norway
Date: 11-Jan-2008 09:03:04
PAGE: 1 of 1
Document number: AVR32905
Revision B
TITLE: PCI-ATA card for STK1000
pci-ata.Sch