

Affected Catalog Part Numbers (CPN):

MCP33141-10-E/MNVAO

MCP33141-10T-E/MNVAO

MCP33151D-10-E/MN

MCP33151D-05-E/MN

MCP33151-10-E/MN

MCP33151-05-E/MN

MCP33141D-10-E/MN

MCP33141D-05-E/MN

MCP33141-10-E/MN

MCP33141-05-E/MN

MCP33151D-10T-E/MN

MCP33151D-05T-E/MN

MCP33151-10T-E/MN

MCP33151-05T-E/MN

MCP33141D-10T-E/MN

MCP33141D-05T-E/MN

MCP33141-10T-E/MN

MCP33141-05T-E/MN

MCP33111D-10-E/MN

MCP33111D-05-E/MN

MCP33111-10-E/MN

MCP33111-05-E/MN

MCP33121D-10-E/MN

MCP33121D-05-E/MN

MCP33121-10-E/MN

MCP33121-05-E/MN

MCP33131D-10-E/MN

MCP33131D-05-E/MN

MCP33131-10-E/MN

MCP33131-05-E/MN

MCP33111D-10T-E/MN

MCP33111D-05T-E/MN

---

DSNO-10PXZY649 - CCB 7314 Final Notice: Qualification of ATP7 as an additional assembly site for selected MCP33111, MCP33111D, MCP33121, MCP33121D, MCP33131, MCP33131D, MCP33141, MCP33141D, MCP33151 and MCP33151D device families available in 10L TDFN (3x3x0.8mm) package.

---

MCP33111-10T-E/MN

MCP33111-05T-E/MN

MCP33121D-10T-E/MN

MCP33121D-05T-E/MN

MCP33121-10T-E/MN

MCP33121-05T-E/MN

MCP33131D-10T-E/MN

MCP33131D-05T-E/MN

MCP33131-10T-E/MN

MCP33131-05T-E/MN

MCP33151-025-E/MN

MCP33151-025T-E/MN

MCP33141D-025-E/MN

MCP33141-025-E/MN

MCP33151D-025T-E/MN

MCP33141D-025T-E/MN

MCP33141-025T-E/MN

MCP33151D-025-E/MN