

Affected Catalog Part Numbers (CPN):

ATTINY461A-XUR

ATTINY261A-XU

ATTINY261A-XUR

ATTINY861A-XU

ATTINY861A-XUR

ATTINY461A-XU

ATTINY45-20XU

ATTINY45V-10XU

ATTINY45-20XUR

ATTINY45V-10XUR

ATTINY20-XU

ATTINY20-XUR