

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts	
HV9910CLG-G	HV9910BLG-G, HV9961LG-G	Pin to Pin	<a href="#">Contact Your Local Sales Office</a>
HV9910CSG-G	HV9910BLG-G, HV9961LG-G	Pin to Pin, No heat slug	<a href="#">Contact Your Local Sales Office</a>
HV9910CNG-G	HV9910BNG-G, HV9961NG-G	Pin to Pin	<a href="#">Contact Your Local Sales Office</a>
HV9803BLG-G	HV9961LG-G	Same package but different pin allocation	<a href="#">Contact Your Local Sales Office</a>
HV9861ALG-G	HV9961LG-G	Pin to Pin	<a href="#">Contact Your Local Sales Office</a>
HV9861ANG-G	HV9961NG-G	Pin to Pin	<a href="#">Contact Your Local Sales Office</a>
MCP1252-33X50I/MS	MCP1256-E/UN	Fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP1252-33X50I/MSVAO	MCP1256-E/UN	Not Automotive qualified, fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP1252-ADJI/MS	MCP1256-E/UN	Fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP1253-33X50I/MS	MCP1256-E/UN	Fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP1253T-33X50E/MSVAO	MCP1256-E/UN	Not Automotive qualified, fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP1252T-33X50I/MS	MCP1256T-E/UN	Fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP1252T-ADJI/MS	MCP1256T-E/UN	Fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts	
MCP1253-ADJI/MS	MCP1256T-E/UN	Fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP1253T-33X50I/MS	MCP1256T-E/UN	Fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP1253T-ADJI/MS	MCP1256T-E/UN	Fixed 3.3V output, regulated positive charge pumps, same output current 120mA, different package MSOP-10 not MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
TC1240AECSTR	MCP1259T-E/MF	Different package DFN-10, not SOT23-6, output regulated charge pump delivering 3.3V from 1.8V to 3.6V, bigger current 100mA	<a href="#">Contact Your Local Sales Office</a>
TC1240ECHTR	MCP1259T-E/MF	Different package DFN-10, not SOT23-6, output regulated charge pump delivering 3.3V from 1.8V to 3.6V, bigger current 100mA	<a href="#">Contact Your Local Sales Office</a>
MCP1603-330I/MC	MCP1602-330I/MF	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1601-I/MS	MCP1602-ADJI/MF	Not pin-compatible. MCP1602 adds PG and VCC pins. MCP1602 does not have SYNC/PWM pin. MCP1602 does not have LDO mode. MCP1602 runs at higher switching frequency.	<a href="#">Contact Your Local Sales Office</a>
MCP1603-ADJI/MC	MCP1602-ADJI/MF	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603LT-120I/OS	MCP1602T-120I/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603T-120I/OS	MCP1602T-120I/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603LT-150I/OS	MCP1602T-150I/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603LT-180I/OS	MCP1602T-180I/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603T-180I/OS	MCP1602T-180I/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts	
MCP1603T-330I/MC	MCP1602T-330I/MF	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603BT-330I/OS	MCP1602T-330I/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603LT-330I/OS	MCP1602T-330I/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603T-330I/OS	MCP1602T-330I/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603T-ADJI/MC	MCP1602T-ADJI/MF	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1601T-I/MS	MCP1602T-ADJI/MS	Not pin-compatible. MCP1602 adds PG and VCC pins. MCP1602 does not have SYNC/PWM pin. MCP1602 does not have LDO mode. MCP1602 runs at higher switching frequency.	<a href="#">Contact Your Local Sales Office</a>
MCP1603BT-ADJI/OS	MCP1602T-ADJI/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP1603T-ADJI/OS	MCP1602T-ADJI/MS	Not pin-compatible. Different package. MCP1602 adds PG, VCC, and AGND pins	<a href="#">Contact Your Local Sales Office</a>
MCP73828-4.1VUA	MCP73113-16SI/MF	DFN-10 instead of MSOP-8, need PCB redesign, Internal FET	<a href="#">Contact Your Local Sales Office</a>
MCP73841-410I/UN	MCP73113-16SI/MF	No TEMP monitor, not same package, DFN-10 instead MSOP-10, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73843-410I/MS	MCP73113-16SI/MF	Internal FET, not same package, DFN 10 instead MSOP-8, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73853-I/ML	MCP73113-16SI/MF, MCP73114-0NSI/MF	DFN-10 instead of QFN-16, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73855-I/MF	MCP73113-16SI/MF, MCP73114-0NSI/MF	DFN-10 same package different pin allocation, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts	
MCP73841T-410I/UN	MCP73113T-16SI/MF	No TEMP monitor, not same package, DFN-10 instead MSOP-10, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73843T-410I/MS	MCP73113T-16SI/MF	Internal FET, not same package, DFN 10 instead MSOP-8, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73853T-I/ML	MCP73113T-16SI/MF, MCP73114T-0NSI/MF	DFN-10 instead of QFN-16, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73855T-I/MF	MCP73113T-16SI/MF, MCP73114T-0NSI/MF	DFN-10 same package different pin allocation, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73841-420I/UN	MCP73114-0NSI/MF	No TEMP monitor, not same package, DFN-10 instead MSOP-10, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73841T-420I/UN	MCP73114-0NSI/MF	No TEMP monitor, not same package, DFN-10 instead MSOP-10, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73843-420I/MS	MCP73114-0NSI/MF	Internal FET, not same package, DFN 10 instead MSOP-8, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73828-4.2VUA	MCP73114-0NSI/MF, MCP73113-06SI/MF	DFN-10 instead of MSOP-8, need PCB redesign, Internal FET	<a href="#">Contact Your Local Sales Office</a>
MCP73842-840I/UN	MCP73213-A6SI/MF	Internal FET, no Temp monitor, not same package, DFN-10 instead MSOP-10, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73844-840I/MS	MCP73213-A6SI/MF	Internal FET, not same package, DFN 10 instead MSOP-8, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73842-820I/UN	MCP73213-B6SI/MF	Internal FET, no Temp monitor, not same package, DFN-10 instead MSOP-10, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73842T-840I/UN	MCP73213T-A6SI/MF	Internal FET, no Temp monitor, not same package, DFN-10 instead MSOP-10, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73844T-840I/MS	MCP73213T-A6SI/MF	Internal FET, not same package, DFN 10 instead MSOP-8, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts	
MCP73844-820I/MS	MCP73213T-B6SI/MF	Internal FET, not same package, DFN 10 instead MSOP-8, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73844T-820I/MS	MCP73213T-B6SI/MF	Internal FET, not same package, DFN 10 instead MSOP-8, internal FET not External, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
MCP73827-4.2VUA	MCP73831T-2ACI/OT,MCP73832-2ACI/MC	DFN-8/SOT23-5 instead of MSOP-8, need PCB redesign	<a href="#">Contact Your Local Sales Office</a>
TC1046VNBTR	MCP9700T-E/TT	Similar, 10mV/C	<a href="#">Contact Your Local Sales Office</a>
TC1047AVNBTR	MCP9700BT-E/TT	<a href="#">Contact Your Local Sales Office</a>	
TC1047AVNBTR-V01	MCP9700BT-E/TT	<a href="#">Contact Your Local Sales Office</a>	
TC1047AVNBTR-V04	MCP9700BT-E/TT	<a href="#">Contact Your Local Sales Office</a>	
TC1047AVNBTR-V10	MCP9700BT-E/TT	<a href="#">Contact Your Local Sales Office</a>	
TC1047AVNBTR-VAO	MCP9700BT-E/TT	<a href="#">Contact Your Local Sales Office</a>	
TC1047VNBTR	MCP9700BT-E/TT	<a href="#">Contact Your Local Sales Office</a>	
TC6501P045VCTTR	MCP9501	<a href="#">Contact Your Local Sales Office</a>	
TC6501P065VCTTR	MCP9501	<a href="#">Contact Your Local Sales Office</a>	
TC6501P085VCTTR	MCP9501	<a href="#">Contact Your Local Sales Office</a>	

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC6501P095VCTTR	MCP9501	<a href="#">Contact Your Local Sales Office</a>
TC6501P105VCTTR	MCP9501PT-105E/OT	<a href="#">Contact Your Local Sales Office</a>
TC6501P115VCTTR	MCP9501PT-115E/OT	<a href="#">Contact Your Local Sales Office</a>
TC6501P120VCTTR	MCP9501PT-105E/OT	<a href="#">Contact Your Local Sales Office</a>
TC6501P125VCTTR	MCP9501PT-125E/OT	<a href="#">Contact Your Local Sales Office</a>
TC6502P045VCTTR	MCP9502	<a href="#">Contact Your Local Sales Office</a>
TC6502P065VCTTR	MCP9502	<a href="#">Contact Your Local Sales Office</a>
TC6502P095VCTTR	MCP9502	<a href="#">Contact Your Local Sales Office</a>
TC6502P105VCTTR	MCP9502	<a href="#">Contact Your Local Sales Office</a>
TC6502P115VCTTR	MCP9502	<a href="#">Contact Your Local Sales Office</a>
TC6504N015VCTTR	MCP9504	<a href="#">Contact Your Local Sales Office</a>
TC6504P005VCTTR	MCP9504	<a href="#">Contact Your Local Sales Office</a>
TCN75-3.3MOA	TCN75AVOA713	<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TCN75-3.3MOA713	TCN75AVOA713	<a href="#">Contact Your Local Sales Office</a>
TCN75-3.3MUA	TCN75AVUOA713	<a href="#">Contact Your Local Sales Office</a>
TCN75-3.3MUA713	TCN75AVUOA713	<a href="#">Contact Your Local Sales Office</a>
TCN75-5.0MOA	TCN75AVOA713	<a href="#">Contact Your Local Sales Office</a>
TCN75-5.0MOA713	TCN75AVOA713	<a href="#">Contact Your Local Sales Office</a>
TCN75-5.0MUA	TCN75AVUOA713	<a href="#">Contact Your Local Sales Office</a>
TCN75-5.0MUA713	TCN75AVUOA713	<a href="#">Contact Your Local Sales Office</a>
CL220K4-G	<a href="#">Contact Your Local Sales Office</a>	
CL220N5-G	<a href="#">Contact Your Local Sales Office</a>	
HV9150K6-G	<a href="#">Contact Your Local Sales Office</a>	
TC72-2.8MMFTR	<a href="#">Contact Your Local Sales Office</a>	
TC72-2.8MUA	<a href="#">Contact Your Local Sales Office</a>	
TC72-3.3MMF	<a href="#">Contact Your Local Sales Office</a>	

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC72-3.3MMFTR		<a href="#">Contact Your Local Sales Office</a>
TC72-3.3MUA		<a href="#">Contact Your Local Sales Office</a>
TC72-3.3MUATR		<a href="#">Contact Your Local Sales Office</a>
TC72-5.0MMF		<a href="#">Contact Your Local Sales Office</a>
TC72-5.0MUA		<a href="#">Contact Your Local Sales Office</a>
TC72-5.0MUATR		<a href="#">Contact Your Local Sales Office</a>
TC77-3.3MCTTR		<a href="#">Contact Your Local Sales Office</a>
TC77-3.3MOA		<a href="#">Contact Your Local Sales Office</a>
TC77-3.3MOATR		<a href="#">Contact Your Local Sales Office</a>
TC77-5.0MCTTR		<a href="#">Contact Your Local Sales Office</a>
TC77-5.0MOA		<a href="#">Contact Your Local Sales Office</a>
TC77-5.0MOATR		<a href="#">Contact Your Local Sales Office</a>
TC642BEOA		<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC642BEOA713		<a href="#">Contact Your Local Sales Office</a>
TC642BEPA		<a href="#">Contact Your Local Sales Office</a>
TC642BEUA		<a href="#">Contact Your Local Sales Office</a>
TC642BEUA713		<a href="#">Contact Your Local Sales Office</a>
TC642COA		<a href="#">Contact Your Local Sales Office</a>
TC642COA713		<a href="#">Contact Your Local Sales Office</a>
TC642EOA		<a href="#">Contact Your Local Sales Office</a>
TC642EOA713		<a href="#">Contact Your Local Sales Office</a>
TC642VOA713		<a href="#">Contact Your Local Sales Office</a>
TC646BEOA		<a href="#">Contact Your Local Sales Office</a>
TC646BEOA713		<a href="#">Contact Your Local Sales Office</a>
TC646BEUA		<a href="#">Contact Your Local Sales Office</a>
TC646BEUA713		<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC646EOA		<a href="#">Contact Your Local Sales Office</a>
TC646VOA		<a href="#">Contact Your Local Sales Office</a>
TC647BEOA		<a href="#">Contact Your Local Sales Office</a>
TC647BEOATR		<a href="#">Contact Your Local Sales Office</a>
TC647BEUA		<a href="#">Contact Your Local Sales Office</a>
TC647BEUATR		<a href="#">Contact Your Local Sales Office</a>
TC647EOA		<a href="#">Contact Your Local Sales Office</a>
TC647VOA		<a href="#">Contact Your Local Sales Office</a>
TC647VOATR		<a href="#">Contact Your Local Sales Office</a>
TC648BEOA		<a href="#">Contact Your Local Sales Office</a>
TC648BEOA713		<a href="#">Contact Your Local Sales Office</a>
TC648BEPA		<a href="#">Contact Your Local Sales Office</a>
TC648BEUA		<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC648BEUA713		<a href="#">Contact Your Local Sales Office</a>
TC648EOA		<a href="#">Contact Your Local Sales Office</a>
TC648EOA713		<a href="#">Contact Your Local Sales Office</a>
TC648EUA		<a href="#">Contact Your Local Sales Office</a>
TC648EUA713		<a href="#">Contact Your Local Sales Office</a>
TC648VOA		<a href="#">Contact Your Local Sales Office</a>
TC648VOA713		<a href="#">Contact Your Local Sales Office</a>
TC648VPA		<a href="#">Contact Your Local Sales Office</a>
TC649BEOA		<a href="#">Contact Your Local Sales Office</a>
TC649BEOATR		<a href="#">Contact Your Local Sales Office</a>
TC649BEPA		<a href="#">Contact Your Local Sales Office</a>
TC649BEUA		<a href="#">Contact Your Local Sales Office</a>
TC649BEUATR		<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC649EOA		<a href="#">Contact Your Local Sales Office</a>
TC649EOATR		<a href="#">Contact Your Local Sales Office</a>
TC650ACVUA		<a href="#">Contact Your Local Sales Office</a>
TC650ACVUATR		<a href="#">Contact Your Local Sales Office</a>
TC650AEVUA		<a href="#">Contact Your Local Sales Office</a>
TC650AEVUATR		<a href="#">Contact Your Local Sales Office</a>
TC650AEVUATR-V01		<a href="#">Contact Your Local Sales Office</a>
TC650AGVUA		<a href="#">Contact Your Local Sales Office</a>
TC650AGVUATR		<a href="#">Contact Your Local Sales Office</a>
TC650BEVUA		<a href="#">Contact Your Local Sales Office</a>
TC650BEVUATR		<a href="#">Contact Your Local Sales Office</a>
TC650CGVUA		<a href="#">Contact Your Local Sales Office</a>
TC650CGVUATR		<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC651ACVUA		<a href="#">Contact Your Local Sales Office</a>
TC651ACVUATR		<a href="#">Contact Your Local Sales Office</a>
TC651ADVUA		<a href="#">Contact Your Local Sales Office</a>
TC651ADVUATR		<a href="#">Contact Your Local Sales Office</a>
TC651AEVUA		<a href="#">Contact Your Local Sales Office</a>
TC651AEVUATR		<a href="#">Contact Your Local Sales Office</a>
TC651AGVUA		<a href="#">Contact Your Local Sales Office</a>
TC651AGVUATR		<a href="#">Contact Your Local Sales Office</a>
TC651BEVUA		<a href="#">Contact Your Local Sales Office</a>
TC651BEVUATR		<a href="#">Contact Your Local Sales Office</a>
TC651CGVUA		<a href="#">Contact Your Local Sales Office</a>
TC651CGVUATR		<a href="#">Contact Your Local Sales Office</a>
TC652AEVUA		<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC652AEVUATR		<a href="#">Contact Your Local Sales Office</a>
TC652AGVUA		<a href="#">Contact Your Local Sales Office</a>
TC652CGVUA		<a href="#">Contact Your Local Sales Office</a>
TC652CGVUATR		<a href="#">Contact Your Local Sales Office</a>
TC653AEVUA		<a href="#">Contact Your Local Sales Office</a>
TC653BEVUA		<a href="#">Contact Your Local Sales Office</a>
TC653BEVUATR		<a href="#">Contact Your Local Sales Office</a>
TC653CGVUA		<a href="#">Contact Your Local Sales Office</a>
TC654EUN		<a href="#">Contact Your Local Sales Office</a>
TC654EUNTR		<a href="#">Contact Your Local Sales Office</a>
TC655EUN		<a href="#">Contact Your Local Sales Office</a>
TC655EUNTR		<a href="#">Contact Your Local Sales Office</a>
TC664EUN		<a href="#">Contact Your Local Sales Office</a>

## PCN\_DSNO-21PDJY950

EOL Catalog Part Number (CPN)	Recommended Replacement Parts	Notes about Recommended Replacement Parts
TC664EUNTR		<a href="#">Contact Your Local Sales Office</a>
TC665EUN		<a href="#">Contact Your Local Sales Office</a>
TC670ECHTR		<a href="#">Contact Your Local Sales Office</a>
TC1320EOA		<a href="#">Contact Your Local Sales Office</a>
TC1320EOATR		<a href="#">Contact Your Local Sales Office</a>
TC1320EUATR		<a href="#">Contact Your Local Sales Office</a>
TC1321EOA		<a href="#">Contact Your Local Sales Office</a>
TC1321EOATR		<a href="#">Contact Your Local Sales Office</a>
TC1321EUA		<a href="#">Contact Your Local Sales Office</a>
TC1321EUATR		<a href="#">Contact Your Local Sales Office</a>